## **Project Information**

**FORM** 

Form Type:

PWC-100

**Project Award Date:** 

7/26/2022

AWARDING BODY INFORMATION

Name:

County of Ventura

**Primary Contact:** 

Terry Smith

Address:

800 S. Victoria Ave.

Primary Email:

Work Phone:

terry\_smith@ventura.org 8056543984

Ventura, CA 93009 PROJECT INFORMATION

**Project Name:** 

Pavement Resurfacing - Las Posas Valley & Balcom Canyon Road

Attention ESD Dept. L1670

Project #:

50627

**Brief Description:** 

Road Improvement to include paving and restriping

Contract #:

RD22-10

**Contract Amount:** 

\$2359167.15

**Total Project Cost:** 

\$2359167.15

Number of Prime Contractors:

Alternative Model:

None Apply

Description of Location:

Various roads near HWY 118 and Balcom Canyon Road near Somis

County:

**VENTURA** 

## **Project Information 2**

**PWC-100** 

Project Name: Pavement Resurfacing - Las Posas Valley & Balcom Canyon Road

Project #: 50627

Contract #: RD22-10

Status: New Submission

**PROJECT INFORMATION** 

**Project Dates** 

First Advertised Bid:

5/19/2022

**Estimated or Actual Start:** 

8/23/2022

**Estimated or Actual** Completion:

10/27/2022

**Propositions** 

Will this project receive (or has it received) any funding from Proposition 84 (The Safe Drinking Water, Water Quality and

Supply, Flood Control, River and Coastal Protection Bond Act of 2006)?

No

Will this project receive (or has it received) any funding from Proposition 39 (California Clean Energy Jobs Act of 2012)?

Compliance and Agreements:

Is language included in the Contract Award to effectuate the requirements of Section 1771, 1774 - 1776, 1777.5,1813 and

1815 of the Labor Code?

Will you operate a DIR-Approved Labor Compliance Program(LCP) for this project?

No

Is there a Project Labor Agreement (PLA) associated with this project?

Nο

## Contractor Information

**Project Manager** 

**Email Address** 

igarcia@carasmussen.com

Name

Jesus Garcia

Project Manager

Work Phone 661-367-9040

General Contractor1

|       | CSLB/Certificate<br>Number | NAME                                    | Address                                       | Email                             | Classification                                    |
|-------|----------------------------|---|---|-----------------------------------|---|
|       | 110000110726               | RUBBERIZED CRACKFILLER<br>SEALANT, INC. | 800 E. WALNUT AVE<br>FULLERTON, CA 92831      | CRACKFILL@GMAIL.COM               | OPERATING ENG<br>LABORERS                         |
| Prime | 1000000274                 | C. A. RASMUSSEN, INC.                   | 28548 LIVINGSTON AVENUE<br>VALENCIA, CA 91355 | DTELLEZ@CARASMUSSEN.COM           | LABORERS<br>OPERATING ENG                         |
|       | 1000000752                 | SUPER SEAL & STRIPE                     | 310 A STREET<br>FILLMORE, CA 93015            | JASMINE@SUPERSEALANDSTRIPE.COM    | OPERATING ENG<br>LABORERS                         |
|       | TOUGHDUANG                 |   | 727 GLENDORA AVE.<br>LA PUENTE, CA 91744      | MORONIA@ACEFENCECOMPANY.COM       | IRON WORKERS OPERATING ENG CEMENT MASONS LABORERS |
|       | 11000001896                | CALIFORNIA GRINDING<br>SPECIALTIES, INC | 1100 JAMES ROAD<br>BAKERSFIELD, CA 93308      | PAUSTIN@AUSTIN-ENTERPRISE.COM     | OPERATING ENG<br>LABORERS                         |
|       | 110000001207               |   | 1012 11TH ST STE 1000<br>MODESTO, CA 95354    | PCALL@AMERICANPAVEMENTSYSTEMS.COM | OPERATING ENG<br>LABORERS                         |
|       | 1000000645                 | AMERICAN ASPHALL SOUTH INC.             | 19792 EL RIVINO ROAD<br>BLOOMINGTON, CA 92509 | RICKE@AMERICANASPHALTSOUTH.COM    | OPERATING ENG<br>LABORERS                         |

Excavation for trenching over 5' deep.

Traffic will be affected on the following roads:

HWY118, Balcom Canyon Rd, Bradley Rd., Bixby Rd., Aspen, Creston Lane North, Heatherton Dr., Kingsgrove Dr. East, Palomino Circle, Palomino Dr. & La Cumbre Rd.

Roads may be restricted to one half of the road, Temporary lane closures with traffic control and signage at either direction.